



5 Mile Pass Quarry
801-616-5422
Mile Marker 16 SR 73
Fairfield, UT



Dirty Sand

Material Applications

- Pipe Bedding
- Fill
- Corrals
- Other Sand Applications

Material Gradation

<u>Sieve Size</u>	<u>Passing</u>
#4	100 %
#10	88 %
#16	80 %
#40	67 %
#100	56 %
#200	42.3 %

